



REES N.D.T. INSPECTION SERVICES 2008 LTD.



15612-89 Street
Grande Prairie, AB T8V 2N8

Grande Prairie
(780) 539-3594
(780) 532-8047 (Fax)

Dispatch
1-888-540-3594
www.reesndt.com

Bonnyville
(780) 573-7630
Email: ronvader@reesndt.com

INSPECTION DATE: 05-Apr-12

CLIENT: Pathmaker Services Co. Ltd.
ADDRESS: RR #1, Site 7, Box 25
Grande Prairie AB T8V 2Z8

REES NDT PO NUMBER: R21103
CLIENT PO NUMBER:
REES NDT WO NUMBER: 137708

CAODC LEVEL IV INSPECTION CERTIFICATE

CERTIFICATION OF: Side Door Elevator Assembly

MAKE: Web Wilson

MODEL: 10 3/4" Side Door

SERIAL NUMBER: JOH 1003

CAPACITY: 50 ton

OWNER: Pathmaker Services Co. Ltd.

REPAIRS/MECHANICAL COMPLETED BY: Guardian IPM

Rees NDT Inspection Services 2008 Ltd. performed a VISUAL AND WET FLUORESCENT MAGNETIC PARTICLE inspection on the above mentioned SIDE DOOR ELEVATOR ASSEMBLY. All observations have been recorded and are disclosed in the Rees NDT Inspection Report for Work Order #137708. The scope of this certificate is limited to the inspection of item's structural condition at the time of inspection and does not imply a review of the equipment's design or its associated capacity rating. The capacity noted above reflects the original equipment manufacturer's maximum capacity rating and may be reduced by operating conditions, regulatory requirements and the use of auxillary equipment that has a lower capacity rating.

The undersigned Engineer reviewed all the inspection reports and has issued this certificate after all required repairs (if any) were completed. In the undersigned Engineer's opinion, the SIDE DOOR ELEVATOR ASSEMBLY may be returned to service and operated within the original manufacturer's specifications. The equipment owner is obliged to supply the OEM's operating instructions with the equipment and maintain the OEM's identification and capacity markings. If OEM information cannot be obtained, certified replacements must be obtained from a Professional Engineer.

This certification covers the above mentioned unit for a period of 500 WORKING DAYS AS PER CAODC RECOMMENDED PRACTICE 2.0 from the date of inspection, or until the unit is damaged by handling, transportation or operation.

Reviewed By:

