

August 29, 2014

Pathmaker Service Co. Ltd.  
100,9215-154 Avenue  
Grande Prairie, Alberta  
T8V 0L5

---

### Equipment Certification

<b>Rig No.:</b>	<b>N/A</b>
<b>Equipment:</b>	<b>RT Perfection Links</b>
<b>Model:</b>	<b>1 3/4" x 40" x 80 Ton</b>
<b>Customer P.O.:</b>	<b>N/A</b>
<b>Serial No.:</b>	<b>10310-R-1037 // 10310-L-1037</b>
<b>Inspection Report No.:</b>	<b>H-31061</b>
<b>Alco Sales/Engineering No.:</b>	<b>52163-E</b>
<b>APEGGA Permit to Practice No.:</b>	<b>P10702</b>
<b>Alco Shop Work Order # :</b>	<b>N/A</b>

---

The above-mentioned perfection links required a Level IV inspection (as per Canadian Association of Oilwell Drilling Contractors, R.P. 4.0), applicable repairs, and certification for service.

A magnetic particle (MT) inspection was conducted on Aug 22, 2014, after the perfection links were completely disassembled and sandblasted.

Repair procedures were developed based on the MT inspection report as well as a thorough visual examination performed by qualified personnel with Alco Inc.

Based on the final inspection on Aug 29, 2014, after load testing, it is our opinion that the perfection links are a safe operating unit and may be returned to service within the manufacturer's original rating and specification.

This certification is valid for a period of 6 years from the date indicated on the engineer's stamp shown below, as per the recommendations provided by the Canadian Association of Oilwell Drilling Contractors, or until the perfection links have been damaged either as a result of operation, transportation or handling.

