

February 08, 2012

Pathmaker Service Co. Ltd.
Site 7, Box 25, RR #1, Stn. Main
Grande Prairie, Alberta
T8V 2Z8

Certificate of Conformance

Rig No.:	N/A
Equipment:	Bail Link Extension c/w Pins
Model:	250 Ton x 6 ft Long
Customer P.O.:	Kelsey
Serial No.:	DH11047-01 + DH11047-02
Inspection Report No.:	H-N/A
Alco Sales/Engineering No.:	20396-E
APEGGA Permit to Practice No.:	P10702
Alco Shop Work Order # :	N/A

This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

The manufacture's documentation provided for the item(s) listed above indicate conformance to The American Petroleum Institute's (API) section 8a and has been load tested to 1.5 times its rating.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 Operating Days for drilling applications, or 6 years for service applications.

