

December 05, 2011

Pathmaker Service Co. Ltd.  
Site 7, Box 25, RR #1, Stn. Main  
Grande Prairie, Alberta  
T8V 2Z8

---

### Equipment Certification

<b>Rig No.:</b>	N/A
<b>Equipment:</b>	Alco Casing Elevator
<b>Model:</b>	5 1/2" - 90° - DD 150 Ton c/w 4 1/2" Bushing
<b>Customer P.O.:</b>	N/A
<b>Serial No.:</b>	10211
<b>Inspection Report No.:</b>	H-27516
<b>Alco Sales/Engineering No.:</b>	17257-E
<b>APEGGA Permit to Practice No.:</b>	P10702
<b>Alco Shop Work Order # :</b>	16087

---

The above-mentioned elevator required a Level IV inspection (as per Canadian Association of Oilwell Drilling Contractors, R.P. 2.0), applicable repairs, and certification for service.

A magnetic particle (MT) inspection was conducted on November 30, 2011, after the elevator was completely disassembled and sandblasted.

Repair procedures were developed based on the MT inspection report as well as a thorough visual examination performed by qualified personnel with Alco Inc.

Based on the final inspection on December 05, 2011, after load testing, it is our opinion that the elevator is a safe operating unit and may be returned to service within the manufacturer's original rating and specification.

This certification is valid for a period of 500 operating days, as per the recommendations provided by the Canadian Association of Oilwell Drilling Contractors, or until the elevator has been damaged either as a result of operation, transportation or handling.

