



REES N.D.T. INSPECTION SERVICES 2008 LTD.



15612-89 Street
Grande Prairie, AB T8V 2N8

Grande Prairie
(780) 539-3594
(780) 532-8047 (Fax)

Dispatch
1-888-540-3594
www.reesndt.com

Vegreville
(780) 603-4887
Email: gcoers@reesndt.com

INSPECTION DATE: 13-Sep-23

CLIENT: Pathmaker Services Co. Ltd.
ADDRESS: 9215 154 AVE
Grande Prairie AB T8X 0L2

REES NDT PO NUMBER: R76141

CLIENT PO NUMBER:

REES NDT WO NUMBER: 207758

INSPECTION CERTIFICATE

CERTIFICATION OF: Single Joint Casing Elevator Extension

MAKE: Rees NDT Inspectin

MODEL: 183-182

SERIAL NUMBER: RE23-062

CAPACITY: 3 ton

OWNER: Pathmaker Services Co. Ltd.

Rees NDT Inspection Services 2008 Ltd. performed a VISUAL AND NON-DESTRUCTIVE TESTING inspection on the above mentioned SINGLE JOINT CASING ELEVATOR EXTENSION. All observations have been recorded and are disclosed in the complete documentation for Rees NDT Work Order #207758. The scope of this certificate is limited to the inspection of the item's structural condition at the time of inspection and does not imply a review of the equipment's design or its associated capacity rating. The capacity noted above reflects the original equipment manufacturer's maximum capacity rating and may be reduced by operating conditions, regulatory requirements and the use of auxillary equipment that has a lower capacity rating.


The undersigned Engineer reviewed all the inspection reports and has issued this certificate after all required repairs (if any) were completed. In the undersigned Engineer's opinion, the SINGLE JOINT CASING ELEVATOR EXTENSION may be returned to service and is safe to use within the original manufacturer's specifications. The equipment owner is obliged to supply the OEM's operating instructions with the equipment and maintain the OEM's identification and capacity markings. If OEM information cannot be obtained, certified replacements must be obtained from a Professional Engineer.

This certification covers the above mentioned unit for a period of 1 YEAR from the date of inspection, or until the unit is damaged by handling, transportation or operation.

Reviewed
By:



14-Sep-2023



Inspected By: K. Millier CWB #5005952 (Level I) SNT #062 (MPI II) Welder (223643A) K. Gejdos Millwright (J-09-31585) Machinist (J-11-16754) J. Ibarbia

Non-destructive Testing · Wall Thickness Testing · Hardness Testing · Crane & Picker Certification · Drilling Rig Certification