



## REES N.D.T. INSPECTION SERVICES 2008 LTD.



15612-89 Street Grande Prairie, AB T8V 2N8

Grande Prairie (780) 539-3594 (780) 532-8047 (Fax)

Dispatch 1-888-540-3594 www.reesndt.com Bonnyville (780) 573-7630 Email: ronvader@reesndt.com

INSPECTION DATE: 03-Jun-13

CLIENT: Pathmaker Services Co. Ltd. ADDRESS: RR #1, Site 7, Box 25

Grande Prairie AB T8V 2Z8

11-Jun-2013

REES NDT PO NUMBER: R25387

CLIENT PO NUMBER:

REES NDT WO NUMBER: 144681

## **CAODC LEVEL IV INSPECTION CERTIFICATE**

CERTIFICATION OF: Single Joint Pickup Elevator

MAKE: Web Wilson

MODEL: 7 5/8 - 8 5/8

SERIAL NUMBER: PU 858

CAPACITY: 5 ton

OWNER: Pathmaker Services Co. Ltd.

REPAIRS/MECHANICAL COMPLETED BY: Rees NDT

Rees NDT Inspection Services 2008 Ltd. performed a VISUAL, WET FLUORESCENT MAGNETIC PARTICLE AND LOAD TEST inspection on the above mentioned SINGLE JOINT PICKUP ELEVATOR. All observations have been recorded and are disclosed in the Rees NDT Inspection Report for Work Order #144681. The scope of this certificate is limited to the inspection of item's structural condition at the time of inspection and does not imply a review of the equipment's design or its associated capacity rating. The capacity noted above reflects the original equipment manufacturer's maximum capacity rating and may be reduced by operating conditions, regulatory requirements and the use of auxillary equipment that has a lower capacity rating.

The undersigned Engineer reviewed all the inspection reports and has issued this certificate after all required repairs (if any) were completed. In the undersigned Engineer's opinion, the SINGLE JOINT PICKUP ELEVATOR may be returned to service and operated within the original manufacturer's specifications. The equipment owner is obliged to supply the OEM's operating instructions with the equipment and maintain the OEM's identification and capacity markings. If OEM information cannot be obtained, certified replacements must be obtained from a Professional Engineer.

This certification covers the above mentioned unit for a period of 500 WORKING DAYS AS PER CAODC RECOMMENDED PRACTICE 2.0 from the date of inspection, or until the unit is damaged by handling, transportation or operation.

Reviewed By:

PERMIT TO PRACTICE
REES NOT ENGINEERING LTD.

Signature \_

Date

11-Jun-2013

## PERMIT NUMBER: P 11509

The Association of Professional Engineers, Geologists and Geophysicists of Alberta